


VCOM 3.6.2 installation for Windows 8 and 10

1. Install VCOM_v3.6.1.exe
2. Go to C:\Program Files (x86)\IC Plus corp\VCOM and right-click on the file called winpcap.exe and select "Properties". Go to the Compatibility tab and select Windows 7 in the "Run this program in compatibility mode for:" section. Click the OK button.



3. Run the file winpcap.exe
4. After winpcap.exe installation is complete Windows 8 will run VCOM_v3.6.1 with winpcap.exe in Windows 7 mode.
5. Alternatively you can download the latest version of Winpcap from <https://www.winpcap.org/>